



Publ. number	Issue Date	TC Holder	Type	Subject
BR-2020-07-02	2020-07-24	YABORA INDUSTRIA AERONAUTICA S.A.	EMB-135, EMB-145	Engine Fuel & Control - Full Authority Digital Engine Control - Software Update
US-2020-16-51	2020-07-24	BOEING	737	Engine Bleed Stage 5 Check Valves - Inspection
ISR-I-53-19-10-5	2020-07-23	GULFSTREAM (GALP)	G280	Forward Fuel Tank Probes Clearance Verification
2020-0165	2020-07-23	AIRBUS	A318, A319, A320, A321	Landing Gear - Nose Landing Gear Main Fitting - Replacement [Reduced Life Limit]
2015-0226R5	2020-07-23	AIRBUS HELICOPTERS, AIRBUS HELICOPTERS DEUTSCHLAND , BELL TEXTRON CANADA LTD (BTCL), BELL TEXTRON INC. (BTI), LEONARDO S.p.A. HELICOPTERS, MD HELICOPTERS INC (MDHI), SIKORSKY	SA 330 / AS 332 / EC 225, SA/AS 365 / EC 155, EC135/635, MBB-BK 117, 429, 430, 212, 214, 412, A109/A119, AB139/AW139, AB212/AB412, MD900, S-61, S-76, S-92	Equipment / Furnishings - Hoist - Test / Replacement
2020-0164	2020-07-22	AIRBUS HELICOPTERS	EC175	Fuselage - Pylon Skin - Inspection
2020-0163	2020-07-22	AIRBUS	A350	Flight Controls - Slat Transmission Shafts - Inspection
2020-0162	2020-07-21	AIRBUS	A380	Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection
2020-0090R1	2020-07-21	AIRBUS	A350	Indicating / Recording Systems - Integrated Control Panels - Modification; Airplane Flight Manual - Abnormal / Normal Procedures Sections - Amendment
US-2020-14-02	2020-07-21	BOEING	747	[Correction] Fuselage - Bulkhead Structure - Inspection
2020-0161-E	2020-07-17	SAFRAN HELICOPTER ENGINES	ASTAZOU XIV	Engine - Stage 3 Turbine Wheels - Replacement



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2020-25	2020-07-17	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
2020-0160	2020-07-16	PILATUS AIRCRAFT LTD	PC-24	Air Conditioning - Cockpit and Cabin Evaporator Filters - Replacement
2020-0158	2020-07-16	PILATUS AIRCRAFT LTD	PC-24	Air Vehicle Wiring - Electrical Harness Installation - Modification
2020-0157	2020-07-16	AIRBUS	A380	Landing Gear - Gravity Extension System - Inspection / Modification
2020-0159	2020-07-16	AIRBUS DEFENCE & SPACE S.A.	C-295, CN-235	Fuselage - Rear Fuselage / Upper Stringers at Frame 43 - Inspection
US-2020-14-01	2020-07-15	BELL TEXTRON INC. (BTI)	214ST	Main Rotor - Spindle to Yoke Bolts - Removal
BR-2020-07-01	2020-07-15	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 190	Aircraft Flight Manual - Engine N1 Setting Limitation - Amendment
US-2020-14-09	2020-07-15	BOEING	737	Fuel - Kathon FP 1.5 Biocide - Removal / Installation / Airplane Flight Manual Revision
2020-0155	2020-07-14	AIRBUS	A320, A321, A330, A350	Communications / Cabin Systems - Removable Display Unit and Display Docking Station Attachment Interface - Operational Restriction / Inspection
2020-0156	2020-07-14	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Main Rotor Drive - Main Gearbox Magnetic Plug and Oil Filter - Inspection / Modification
US-2020-12-07	2020-07-14	HAMILTON SUNDSTRAND	54H	Propellers - Blades - Inspection / Replacement
CF-2014-07R1	2020-07-14	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Fuselage - Cracking of Skin Panels and Skin Splice Joints and Angles at Stringers 6 and 20 between Fuselage Station 409.00 and 589.00
CF-2020-24	2020-07-13	BOMBARDIER	CL-600 (Challenger)	Navigation - Inertial Reference System (IRS) / Flight Management System (FMS) - Wrong Magnetic Heading Displayed due to Outdated Magnetic Variation (MagVar) Tables