



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0163R1	2020-08-07	AIRBUS	A350	Flight Controls - Slat Transmission Shafts - Inspection
US-2020-16-13	2020-08-07	ROLLS-ROYCE CORPORATION (USA)	AE 3007	Engine - 3rd-Stage Compressor Wheels - Replacement
2020-0176	2020-08-05	AIRBUS	A319, A320, A321	Fuel - Flight with Fuel and KATHON FP 1.5 Biocide Mixture - Prohibition
2020-0173	2020-08-05	ATR	ATR72	Time Limits / Maintenance Checks - Certification Maintenance Requirements and Airworthiness Limitations - Amendment
2020-0175	2020-08-05	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Doors - Sliding Doors - Inspection
2020-0174	2020-08-05	AIRBUS	A318, A319, A320, A321	Wings - Outer Flaps and Tabs - Identification / Inspection (improper heat treatment) / Replacement (wrong material)
BR-2020-06-02R1	2020-08-03	YABORA INDUSTRIA AERONAUTICA S.A.	ERJ 190	Nacelles / Pylons - Pylon Lower Link Fitting Inboard and Outboard Attaching Parts - Inspection / Replacement / Re-torque / Modification
2020-0172	2020-08-03	AIRBUS	A340	Wings - Lower Skin Covers at Rib Bays - Inspection
2020-0141R1	2020-07-30	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor Drive - Main Gearbox Freewheel Shafts - Replacement ; Placards and Markings - ENG1 Training Idle Switch - Installation / Operational Restriction
2017-0198-CN	2020-07-29	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	BR700-710	CANCELLED : Engine Fuel and Control - Engine Electronic Controller Firebox Assembly - Replacement
2020-0168R1	2020-07-29	DASSAULT AVIATION	Falcon 2000, Falcon 900EX, Mystère-Falcon 900	Equipment / Furnishings - Pilot Seat Belt Nuts - Inspection / Replacement
2020-0171	2020-07-28	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Rotors - Main Gearbox Oil Cooling Fan - Inspection / Replacement
2020-0166	2020-07-27	AIRBUS	A350	Fuselage - Seat Track Extremities - Inspection / Repair
2020-0167	2020-07-27	AIRBUS	A350	Flight Control and Guidance System - Ram Air Turbine Performance - Modification (Software Update) ; Air Conditioning - Electrical Power Supply to Air Generation System Ram Air Actuators - Modification



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0169	2020-07-27	AIRBUS	A350	Pneumatic - Bleed Gimbals at Wing to Pylon Interfaces - Inspection / Modification