



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0022R1	2020-09-18	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gear Box / Particle Detectors - Inspection Main Rotor Drive - Planet Gear Assemblies - Replacement / Modification
US-2020-18-14	2020-09-18	GENERAL ELECTRIC	GE90	Engine - High-Pressure Turbine Rotor Stage 2 Disk - Inspection / Replacement
2010-0080-CN	2020-09-16	DASSAULT AVIATION	Mystère-Falcon 50	CANCELLED: Time Limits/Maintenance Checks - Airworthiness Limitations Section - Revision
2020-0198	2020-09-15	AIRBUS	A380	Time Limits / Maintenance Checks - Safe Life Airworthiness Limitations Items - ALS Part 1 - Amendment
US-2020-16-19	2020-09-14	SIKORSKY	S-92	Main Rotor Drive - Auxiliary Circuit Breaker Modification Kits - Installation / Rotorcraft Flight Manual - Update
US-2020-18-51	2020-09-14	APPLIANCES	ATA 34 NAVIGATION	[Final Rule] SANDIA AEROSPACE - Airplane Flight Manual - Section Limitations - Amendment
2020-0163R2	2020-09-10	AIRBUS	A350	Flight Controls - Slat Transmission Shafts - Inspection
2020-0197	2020-09-10	LEONARDO S.p.A. HELICOPTERS	AW169, AW189	Tail Rotor - Tail Rotor Servo Actuator / Duplex Bearing - Inspection / Check / Modification
2020-0196	2020-09-09	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine - High Pressure / Intermediate Pressure Bearing Support Assemblies - Removal from Service
2020-0194	2020-09-08	PILATUS AIRCRAFT LTD	PC-24	Powerplant - Engine Attachment Hardware - Inspection / Replacement
2020-0195	2020-09-08	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - Low Pressure Turbine Discs - Inspection
CF-2020-30	2020-09-07	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuselage - Forward Avionics Bay - Water Ingress from Forward Galley Drains
BR-2020-09-01	2020-09-07	EMBRAER	EMB-505 (Phenom 300)	Stabilizers - Control Surface Mass-balance Weights and Attachments - Inspection / Replacement
2020-0193	2020-09-07	AIRBUS	A318, A319, A320, A321	Landing Gear - Main Landing Gear Sliding Tubes - Inspection / Replacement