



Publ. number	Issue Date	TC Holder	Type	Subject
2020-0283	2020-12-24	AIRBUS	A330, A340	[Correction] Fuel - Fuel Pump - Inspection
2020-0022R2	2020-12-23	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gear Box / Particle Detectors - Inspection; Main Rotor Drive - Planet Gear Assemblies - Replacement / Modification
US-2020-26-04	2020-12-22	BOEING	737	Fuselage - Skin Panels - Inspection / Repair / Installation
2020-0287	2020-12-21	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Tail Rotor Drive - Tail Rotor Drive Flange / Shaft Flexible Coupling - Inspection / Modification
US-2020-24-10	2020-12-21	AEROSTAR AIRCRAFT CORPORATION	PA-60 (Aerostar)	Flight Controls - Elevator and Aileron Balance Tubes - Inspection / Replacement
2018-0168R1	2020-12-18	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Tail Rotor - Blade - Re-identification / Life Limit
2020-0285	2020-12-18	AIRBUS	A380	Indicating / Recording Systems - Flight Data Recording System - Modification (Software Update)
2020-0284	2020-12-18	DASSAULT AVIATION	Falcon 2000, Falcon 7X, Falcon 900EX	Equipment / Furnishings - Cabin Seat Pin and Plate - Inspection
2020-0286	2020-12-18	AIRBUS	A380	Pneumatic - Pylon / Wing Interface Bleed Duct and Fuel Pipe - Inspection
2020-0282	2020-12-17	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Tail Rotor - Blades - Inspection
US-2020-24-04	2020-12-17	BOEING	787	[Correction] Auto Flight - Airplane Flight Manual - Revision
US-2020-26-05	2020-12-17	TEXTRON AVIATION INC.	560/560XL	Throttle Quadrant Assembly Sensor Link and Sensor Drive Arm Pivot - Inspection
2020-0281	2020-12-16	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Equipment / Furnishings - Hoist Control Power Supply - Modification
US-2020-22-10	2020-12-15	BOEING	777	Equipment / Furnishings - Foam Insulation on the Dripshield & Overhead Panel Support Structure - Inspection / Replacement
US-2020-21-17	2020-12-15	BOEING	757	Wings - Wing Skin / Shim - Inspection
CF-2020-30R1	2020-12-14	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuselage - Forward Avionics Bay - Water Ingress from Forward Galley Drains
2020-0280	2020-12-14	AIRBUS	A318, A319, A320	Fuselage - Skin Above Lap Joint - Inspection
2020-0278	2020-12-14	PILATUS AIRCRAFT LTD	PC-6	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment



Publ. number	Issue Date	TC Holder	Type	Subject
US-2020-21-16	2020-12-14	BOEING	747	Wings - Upper Wing Skin, Strut Lower Spar Fitting, Clevis Lugs at End of the Diagonal Brace and Lower Link Fitting - Repetitive Inspections
US-2020-25-12	2020-12-14	LYCOMING ENGINES, SUPERIOR AIR PARTS, INC.	AEIO-360, IO-360, O-360, IO-360, O-360	Reciprocating Engine - Crankshaft Assembly - Removal
2020-0279	2020-12-14	AIRBUS	A330, A340	Navigation - Pitot Probe Attachment Nuts - Re-Torque