



Publ. number	Issue Date	TC Holder	Type	Subject
US-2021-11-16	2021-06-11	PIPER AIRCRAFT INC.	PA-36 (Normal), PA-36 (Restricted)	Wings - Spar Carry-Through Assembly / Structural Components - Inspection / Replacement (Life Limits)
2021-0139	2021-06-11	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - Cabin Lateral Sliding Plug Door Emergency Jettisoning System - Inspection / Modification
2021-0130R1	2021-06-10	AIRBUS	A350	Flight Controls - Slat Geared Rotary Actuators - Drainage / Cleaning
US-2021-11-15	2021-06-09	INTERNATIONAL AERO ENGINES AG	V2500-( )5	Engine - High-Pressure Turbine Disks - Inspection / Replacement
2021-0138	2021-06-09	BOEING, FOKKER SERVICES	747, EASA STC 10068342	Time Limits / Maintenance Checks - Damage Tolerance of Fatigue Critical Structure - Implementation
2021-0137	2021-06-08	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	SAFRAN SEATS - Pilot and Co-pilot Seats / Longitudinal Locking System Pins - Measurement / Adjustment
G-2021-0003	2021-06-08	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	SURVITEC GROUP LIMITED - Halo Passenger Life Jacket - Inspection
2021-0136	2021-06-04	AIRBUS	A330, A340	Equipment / Furnishings - Doghouse Placard - Replacement
2021-0135	2021-06-02	BOEING, LUFTHANSA TECHNIK AG	737, 747, 767, 777, EASA STC 10048788, EASA STC 10053514, EASA STC 10054178, LBA STC TA0352, LBA STC TA0560, LBA STC TA0585, LBA STC TA0745, STC EASA.A.S.00221, STC EASA.A.S.01519, STC EASA.A.S.01692, STC EASA.A.S.02705, STC LBA.21E2.TA0501	Oxygen - Low-Pressure Oxygen Flexible Hoses - Replacement
2021-0134	2021-06-01	AIRBUS	A300	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 / Damage Tolerant Airworthiness Limitation Items - Amendment
US-2021-10-19	2021-05-31	AVIATION PARTNERS BOEING, BOEING	EASA STC 10016394, STC EASA.IM.A.S.02723, STC ST01920SE, 767	Maintenance or Inspection Program - Revision