

Publ. number	Issue Date	TC Holder	Туре	Subject
2021-0191-E	2021-08-20	AUSTRO ENGINE GMBH	E4	[Correction] Engine - Oil Pump - Replacement
2021-0195	2021-08-20	AIRBUS HELICOPTERS	AS 350 / EC 130	Rotorcraft Flight Manual - Engine Digital Electronic Control Unit Emergency Procedure - Amendment
2021-0193	2021-08-20	AIRBUS HELICOPTERS	AS 355	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2021-0194	2021-08-20	AIRBUS HELICOPTERS	AS 350 / EC 130	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2015-0094-CN	2021-08-20	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	CANCELLED: Main Rotor Drive - Bi-Directional Suspension Cross-Bar - Inspection
2010-0006-CN	2021-08-20	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	CANCELLED: Time Limits / Maintenance Checks - Tail Rotor Pitch-Change Links - Inspection
US-2021-17-09	2021-08-19	PRATT & WHITNEY	PW1500G, PW1900G	Engine - High-Pressure Compressor Front Hub and Rotor Shaft - Removal / Replacement
2021-0192	2021-08-18	AIRBUS HELICOPTERS	EC175	Main Rotor - Upper and Lower H legs - Service Life Limit
2021-0190	2021-08-17	AIRBUS	A300, A300-600, A300-600ST (Beluga)	Wings - Main Landing Gear Support Rib 5 - Inspection
US-2021-14-11	2021-08-17	GENERAL ELECTRIC	CF6-80A, CF6-80C	Engine - High-Pressure Turbine Thermal Shield - Inspection
US-2021-15-51	2021-08-17	BELL TEXTRON INC. (BTI)	204B, 205, 212	[Final Rule] Main Rotor - Hub Strap Pins - Replacement
US-2021-13-02	2021-08-13	BOEING	777	Equipment / Furnishings - Insulation Blankets - Installation
CF-2021-27	2021-08-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits / Maintenance Checks - Airworthiness Limitations - Implementation
CF-2021-28	2021-08-12	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Landing Gear - Nose Wheel Steering Hydraulic Motor - Potential Jam Due to Wear
G-2021-0005	2021-08-11	BAE SYSTEMS (OPERATIONS) LTD	Jetstream 3100, Jetstream 3200	Flight Controls - Push Rod Assembly at Gust-lock/Power Lever Baulk Mechanism - Replacement
2017-0032-CN	2021-08-11	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	CANCELLED: Main Rotor - Main Rotor Hub / Mast Attachment Screws - Inspection
2021-0185R1	2021-08-11	APPLIANCES	ATA 26 FIRE PROTECTION	UMLAUT ENGINEERING GmbH - Hand-operated Fire Extinguishers - Inspection / Replacement
US-2021-15-05	2021-08-11	GENERAL ELECTRIC	GE90	Engine Controls - Full Authority Digital Engine Control Integrated Circuit Microprocessor - Replacement
G-2021-0006	2021-08-11	BAE SYSTEMS (OPERATIONS) LTD	ATP	Engine Controls - Power Control - Engine Power Control Cables - Replacement
2021-0189-E	2021-08-09	AERO (PROPELLERS)	ELPROP	Propeller - Propeller Hub - Inspection / Replacement



Publ. number	Issue Date	TC Holder	Туре	Subject
US-2021-16-15	2021-08-09	BOEING	737	Air Conditioning - Failed Air Conditioning Pack Electronic Flow Control in Aft Cargo Compartment - Dispatch Restrictions for Carriage of Cargo
2021-0188	2021-08-09	AIRBUS HELICOPTERS	EC175	Doors - Cargo Door Handle / Locking Mechanism - Inspection / Replacement
2021-0187	2021-08-09	SCHLEICHER, ALEXANDER	ASW 15	Wings - Root Ribs - Inspection

Biweekly 17-2021 Issued on 23/08/2021