



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2022-09	2022-03-04	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Air Conditioning - Avionics Cooling - Integrated Flight Cabinet Failure Due to High Temperatures
CF-2022-08	2022-03-04	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel - Fuel Distribution - Fuel Feed System Damage
US-2022-04-09	2022-03-04	APPLIANCES	ATA 35 OXYGEN	AVOX SYSTEMS INC. - Oxygen Cylinder and Valve Assemblies - Inspection / Replacement
2022-0034	2022-03-04	GE AVIATION CZECH	H75, H80, H85, M601	Engine - Outer Liner Dilution Tube - Inspection
2011-0072-CN	2022-03-04	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	CANCELLED: Equipment / Furnishings - Emergency Flotation Gear Attachment Brackets - Inspection / Replacement
2022-0032	2022-03-03	AIRBUS	A318, A319, A320, A321	Landing Gear - Braking and Steering Control Unit - Replacement / Master Minimum Equipment List - Amendment
2022-0033	2022-03-03	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	BR700-710	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
G-2022-0005	2022-03-03	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ	Navigation - Inertial Reference Units Magnetic Variation - Inspection
CF-2022-06	2022-03-02	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Oxygen System - Crew Oxygen Line Contamination
US-2022-04-04	2022-03-02	CONTINENTAL AEROSPACE TECHNOLOGIES, INC., STRATUS TOOL TECHNOLOGIES, LLC	C-125, C145, IO-360, IO-470, IO-520, IO-550, O-300, O-300 (RR), O-470, TSIO-360, TSIO-520, EASA STC 10040938, EASA STC 10040939, FAA STC SE09356SC, FAA STC SE10348SC, FAA STC SE8409SW	Reciprocating Engine - Oil Filter Adapter Gasket - Replacement
G-2022-0004	2022-03-01	BAE SYSTEMS (OPERATIONS) LTD	HS748	Undercarriage - Nose Landing Gear Axle - Inspection
2020-0227R1	2022-03-01	ATR	ATR72	Electrical Routing - Electrical Harness Routes 1M and 1S-1V - Modification
US-2022-05-04	2022-02-25	BOEING	737	Aircraft Flight Manual - Limitations / Operating Procedures - Amendment
2021-0101R1	2022-02-25	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Doors - Placards - Installation / Rotorcraft Flight Manual - Section Emergency Procedures - Amendment
2022-0030	2022-02-25	AIRBUS	A318, A319, A320, A321	Fuselage - Inner Cap and Frame Flange at Frame 68 Stringer 22 - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0025R1	2022-02-25	AIRBUS	A330, A340	Landing Gear - Main and Centre Landing Gear Bogie Pivot Pins - Inspection / Replacement
2021-0283R1	2022-02-25	AIRBUS HELICOPTERS	AS 350 / EC 130	[Correction] Fuselage - Rear Transmission Bearing Support - Inspection
2022-0031	2022-02-25	AIRBUS	A350	Pneumatic - Overheat Detection System Sensing Elements - Inspection - Master Minimum Equipment List - Temporary Operational Restrictions
US-2022-04-07	2022-02-24	GENERAL ELECTRIC	GEnx	Engine Fuel & Control - Fuel Metering Unit Bypass Valve Plug - Inspection / Replacement
US-2022-05-01	2022-02-24	LEARJET, INC.	31/35/36, 55, 60	Wings - Spoiler Assemblies - Removal
US-2022-03-15	2022-02-24	GARMIN INTERNATIONAL INC.	EASA STC 10073816, EASA STC 10075142, FAA STC SA01899WI, FAA STC SA02658SE	Fuel - Resistive Fuel Probe Interface - Modification
2022-0029-E	2022-02-23	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	MARS A.S.: Emergency Parachutes - Removal from Service
G-2021-0016R1	2022-02-22	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Fuselage - Left Hand Nose Landing Gear Well Sidewall & Retraction Jack Attachment - Inspection
2022-0028	2022-02-22	AIRBUS	A319, A320, A321	Aircraft Flight Manual / Section Normal Procedures - Amendment / Navigation - Master Minimum Equipment List - Integrated Standby Instrument System - Amendment / Flight Controls - Elevator Aileron Computer System - Modification
BR-2022-02-02	2022-02-22	EMBRAER	EMB-545/-550 (Legacy 500)	Flight Controls - Engine Indication and Crew Alert System Software - Update