



Publ. number	Issue Date	TC Holder	Type	Subject
US-2022-21-06	2022-11-10	GENERAL ELECTRIC	CF34-8	Engine - Low Pressure Turbine Stage 5 Discs - Removal / Replacement
US-2022-22-12	2022-11-10	BELL TEXTRON INC. (BTI), ERICKSON 214 HOLDINGS, LLC, LEONARDO S.p.A. HELICOPTERS	204B, 205, 210, 212, 412, 214, AB212/AB412	NOT ADOPTED - EASA DECISION ATTACHED
US-2022-20-15	2022-11-08	BOEING	757	Wings - Centre Wing Box Rear Spar, Lower Skin, Lower Chord - Inspection / Repair
2022-0218	2022-11-08	AIRBUS S.A.S.	A380	Equipment / Furnishings - Fuselage / Belly Fairing Mounted Emergency Evacuation Escape Slides - Replacement
2022-0213R1	2022-11-08	AIRBUS S.A.S.	A318, A319, A320, A321	Doors - Passenger Door / External Handle Mechanism - Cleaning / Lubrication
2022-0217	2022-11-04	AIRBUS S.A.S.	A350	Hydraulic Power - Nose Landing Gear Pressure Return Lines - Replacement
G-2022-0019	2022-11-02	BAE SYSTEMS (OPERATIONS) LTD	Jetstream 4100	Doors - Passenger Door Inner Skin, Edge Member and Seal Carrier adjacent to Roller Brackets - Inspection
US-2022-19-15	2022-11-02	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	[Correction] Engine - High Pressure Turbine Stage 1 / 2 Disks - Inspection / Replacement
2022-0216	2022-11-02	SAAB AB	340	Flight Controls - Stall Warning / Identification System - Modification