



Publ. number	Issue Date	TC Holder	Type	Subject
2021-0166R1	2022-12-22	AIRBUS S.A.S.	A320	Equipment / Furnishings - Passenger Seats - Inspection
CF-2022-70	2022-12-22	AIRBUS CANADA LP	BD-500 (A220 Series)	Fuel Distribution - Motive Flow Fuel-feed Tubes Damaged at Bonding Clamp and Clamp Block Locations Inside the Fuel Tank
2022-0266	2022-12-22	AIRBUS S.A.S.	A318, A319, A320, A321	Electric and Electronic Common Installation - Cockpit Panel Bracket - Inspection
2022-0265	2022-12-21	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine Indicating / Conformation Values - Consistency Check
2022-0262	2022-12-21	AIRBUS S.A.S.	A380	Wings - Front and Rear Spars - Inspection
2022-0263	2022-12-21	AIRBUS S.A.S.	A350	Landing Gear - Main Landing Gear Bogie Pivot Pin - Greasing
2022-0257	2022-12-21	AIRBUS S.A.S.	A340	Fuel - Valves and Pumps - Inspection / Replacement
2021-0101R2	2022-12-21	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Doors - Placards - Installation / Rotorcraft Flight Manual - Section Emergency Procedures - Amendment
2022-0264	2022-12-21	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 900	Engine Fuel & Control - Fuel Pump - Replacement (Life Limitation)
2022-0261	2022-12-20	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Fire Protection - Fire Detectors - Replacement
2022-0260	2022-12-20	FOKKER SERVICES	F28	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Airworthiness Limitations Items and Safe Life Items - Implementation
2022-0258	2022-12-20	LEONARDO S.p.A. HELICOPTERS	AB212/AB412	Main Rotor Drive - Main Transmission Support Case - Inspection / Replacement
2022-0259	2022-12-20	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
US-2022-25-04	2022-12-19	BOEING	747	Equipment / Furnishings - Door 5 Ceiling Stowage Boxes - Replacement / Operation Check
2022-0256	2022-12-19	SAFRAN HELICOPTER ENGINES	ARRIEL 1	Fire Protection - Fire Detectors - Replacement
CF-2022-69	2022-12-19	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Landing Gear - Alternate Extension System - Cam Assembly Failures
ISR-I-24-2018-09-7R2	2022-12-19	GULFSTREAM (GALP)	G150	Electrical Power - Upper and Lower Front Relay Box Replacement
2022-0253	2022-12-19	AIRBUS S.A.S.	A330	Engine Fuel & Control - Engine Electronic Control Software - Modification / Replacement
2022-0254	2022-12-19	SAFRAN HELICOPTER ENGINES	RTM 322	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2022-0255	2022-12-19	SAFRAN HELICOPTER ENGINES	RTM 322	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
CF-2022-68	2022-12-16	BELL TEXTRON CANADA LTD (BTCL)	407	Fuselage - Tailboom - Loss of Tailboom Attachment Hardware



Publ. number	Issue Date	TC Holder	Type	Subject
2022-0252	2022-12-16	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	BR700-715	Engine - Low Pressure Compressor Booster Rotor - Inspection
2022-0240R1	2022-12-15	AUSTRO ENGINE GMBH	E4	Engine - Pistons - Oil Analysis / Replacement
2018-0104R2	2022-12-15	AIRBUS HELICOPTERS	AS 350 / EC 130	Fuselage - Tail Boom / Fenestron Junction Frame - Inspection
2022-0247	2022-12-14	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
2022-0251-E	2022-12-14	AIRBUS HELICOPTERS	AS 350 / EC 130	Tail Rotor Drive - Shaft-Line - Check / Measurement
2022-0249	2022-12-14	PILATUS AIRCRAFT LTD	PC-24	Navigation - Weather Radar System Redundant Wiring - Modification
2022-0248	2022-12-14	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 7000	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
2022-0250	2022-12-14	AIRBUS S.A.S.	A350	Wings - Upper / Lower Wing Skin Cover Edge Glow Sealant - Inspection / Modification
BR-2022-12-01	2022-12-13	EMBRAER S.A.	ERJ 190	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
2022-0246	2022-12-12	AIRBUS HELICOPTERS	AS 350 / EC 130, AS 355	Main Rotor - Main Rotor Blades - Inspection
2022-0245	2022-12-12	PILATUS AIRCRAFT LTD	PC-12	Landing Gear - Nose and Main Landing Gear Actuators - Replacement