



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0100	2024-05-10	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Equipment and Furnishings / Ice and Rain Protection / Fuselage - Dual Hoist Removable Parts or De-icing System - Removal
BR-2023-08-03R2	2024-05-08	EMBRAER	EMB-545/-550 (Legacy 500)	Windows - Cockpit Side Windows - Inspection / Replacement
2024-0099	2024-05-06	AIRBUS S.A.S.	A380	Equipment / Furnishings - Fuselage / Belly Fairing Mounted Emergency Evacuation Escape Slides - Replacement
BR-1999-02-01R7	2024-05-06	EMBRAER S.A.	EMB-145	Aileron PCA Rod Ends and Fittings - Inspections
US-2024-06-01	2024-05-06	BOEING	737	Fuselage - Skin and Bear Strap at the Forward Galley Door Cutout - Inspection
2024-0097	2024-05-02	AIRBUS S.A.S.	A318, A319, A320, A321	Fuselage - Centre Fuselage / Main Landing Gear Door Keel Beam Hinge and Actuator Fittings - Inspection
CF-2023-68R1	2024-05-02	AIRBUS CANADA LP	BD-500 (A220 Series)	Stabilizer - Horizontal Stabilizer - Jamming of the Horizontal Stabilizer Trim Actuator
US-2024-06-14	2024-05-02	INTERNATIONAL AERO ENGINES LLC	PW1100 / PW1400	Engine - High-pressure Compressor 2nd and 4th Stage Rotors - Replacement
US-2024-06-15	2024-05-02	GENERAL ELECTRIC	GE90	Engine - Interstage High-Pressure Turbine Rotor Seal - Inspections
G-2024-0001-E	2024-05-02	LINDSTRAND TECHNOLOGIES	Series 1, Series 2, Series R	Hot Air Balloons - Envelopes with Polyester Filled Aramid (Kevlar) Load Tapes - Removal from Service
2024-0098	2024-05-02	AIRBUS S.A.S.	A350	Fuselage - Forward Cargo Door Piano Hinges - Inspection
US-2024-07-05	2024-05-02	BOEING	757	Fuselage - Station 1640 Frame Web Between S-14 and S-15 - Inspection / Maintenance Records Check
2024-0096	2024-05-02	ATR	ATR42, ATR72	Flight Controls - Rudder Travel Limiting Unit - Inspection
2024-0095	2024-04-30	AIRBUS DEFENCE & SPACE S.A., AIRBUS S.A.S.	EASA STC 10029272, EASA STC 10034690, EASA STC 10035945, EASA STC 10063084, EASA STC 10064192, STC EASA.A.S.02790, A330	Fuselage - Bulk Cargo Door Frames - Inspection / Repair
CF-2024-13	2024-04-30	AIRBUS CANADA LP	BD-500 (A220 Series)	Hydraulic Power - Improperly Torqued Rudder Power Control Unit Hydraulic Fittings



Publ. number	Issue Date	TC Holder	Type	Subject