



Publ. number	Issue Date	TC Holder	Type	Subject
2024-0177	2024-09-13	AIRBUS HELICOPTERS	EC175	Time Limits / Maintenance Checks - Airworthiness Limitations Section / 04-10 Limitations and 04-20 Inspections - Amendment
2024-0101R1	2024-09-13	AIRBUS S.A.S.	A380	Fuel - Engine Low Pressure Shut Off Valve Electrical Harness Routing - Modification
2024-0179-E	2024-09-13	ELIXIR AIRCRAFT	Elixir	Power Plant - Engine Mount Bolts - Replacement
US-2024-15-05	2024-09-12	BOEING	767	Electrical Power - Electrical Support Bracket - Installation / Wire Bundles - Re-installation
CF-2024-32	2024-09-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Electrical System Installation - Frame (FR) 51 Bulkhead Connectors - Inadequate Electrical Bonding
2024-0178	2024-09-12	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000, TRENT 7000	Engine - Intermediate Pressure Compressor Shaft Assembly / Front Air Seal - Inspection
2024-0176	2024-09-11	FOKKER SERVICES	F28	Landing Gear - Main Landing Gear Piston - Inspection
CF-2024-31	2024-09-11	BOMBARDIER	CL-600 (Challenger)	Flight Controls - Flap System On-Board Recorder (FSOBR) effects on Flap Control Unit
2024-0175	2024-09-06	CFM INTERNATIONAL	LEAP-1A/-1C	Engine - Fuel Nozzle - Replacement
2024-0174-E	2024-09-05	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT XWB	Engine - Main Fuel Hose Assembly / Fuel Hoses - Inspection
CF-2024-30	2024-09-04	AIRBUS CANADA LP	BD-500 (A220 Series)	Engine - Airplane Flight Manual (AFM) Non-Normal Procedure - Engine Bleed Duct Large Leak
2024-0173	2024-09-04	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Doors - Jettisonable Windows and Seals on the Sliding Doors and Fixed Panels - Modification