



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2025-42	2025-08-28	BOMBARDIER	BD-100	Flight Controls - Horizontal Stabilizer - Autopilot Inability to Trim Horizontal Stabilizer
ISR-I-27-2025-03-06R1	2025-08-28	GULFSTREAM (GALP)	G280	Flight Controls - Empennage Electrical Harness Retrofit
2025-0187	2025-08-27	AIRBUS HELICOPTERS	EC175	Fuselage - Cockpit Floors - Inspection
2025-0186	2025-08-27	ELIXIR AIRCRAFT	Elixir	Power Plant - Engine Mount - Inspection / Replacement
2025-0142R1	2025-08-27	LEONARDO S.p.A. HELICOPTERS	A109/A119	Rotors Flight Control - Cyclic Control System / Pitch and Roll Actuators Attaching Bolt - Inspection
2025-0185	2025-08-26	AIRBUS S.A.S.	A318, A319, A320, A321	Wings - Pylon Spigot Fitting - Inspections
2025-0184	2025-08-25	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Doors - Sliding / Plugging Cabin Doors - Inspection / Modification
2025-0183	2025-08-25	AIRBUS S.A.S.	A350	Engine Fuel and Control - Hydro-Mechanical Unit - Replacement / Life Limitation
2025-0182	2025-08-25	PILATUS AIRCRAFT LTD	PC-12	Equipment and Furnishings - Emergency Exit / Passenger Service Unit Trim Panel Installation - Modification
CF-2025-41	2025-08-22	BOMBARDIER	BD-700	Equipment/Furnishings - Seats - Missing Loctite
CF-2025-40	2025-08-22	BOMBARDIER	BD-700	Electrical Power - Protective Film Cover on Secondary Power Distribution Assemblies (SPDA) not Removed
US-2025-14-03	2025-08-21	GENERAL ELECTRIC	CF34-10	Turbine Engine - High-Pressure Turbine Front Rotating Air Seal - Inspections
US-2025-15-09	2025-08-21	BOEING	777	Equipment / Furnishings - Flight Crew Seats - Inspection
2025-0181	2025-08-20	AIRBUS S.A.S.	A350	Integrated Modular Avionics - Core Processing Input and Output Module - Replacement
2024-0058R2-CN	2025-08-20	AIRBUS S.A.S.	A350	CANCELLED: Pneumatic - Precooler Exchanger - Inspection