



| Publ. number  | Issue Date | TC Holder                             | Type                                       | Subject                                                                                                                                                                                |
|---------------|------------|---------------------------------------|--------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| US-2025-18-02 | 2025-10-10 | BOEING                                | 787                                        | Oxygen - Passenger Service Unit Oxygen Panel Assemblies - Inspection                                                                                                                   |
| 2025-0221-E   | 2025-10-10 | POLSKIE ZAKLADY LOTNICZE (PZL) MIELEC | M28                                        | Flight Controls - Rudder Control System / Bracket to Frame 29 - Inspection                                                                                                             |
| 2025-0220     | 2025-10-10 | DG AVIATION GmbH                      | DG-1000                                    | Flight Manual - Amendment Powerplant - Operational Restriction Placards and Markings - Placards - Installation                                                                         |
| US-2025-19-11 | 2025-10-09 | BOEING                                | 757                                        | Landing Gear - Main Landing Gear Outer Cylinders - Records Check / Inspection                                                                                                          |
| US-2025-17-11 | 2025-10-09 | MD HELICOPTERS INC (MDHI)             | 369, 500N, 600N                            | Rotors Flight Control - Tail Rotor Pedal Support Brackets - Repetitive Inspections                                                                                                     |
| CF-2025-51    | 2025-10-09 | BOMBARDIER                            | CL-600 (Challenger)                        | Flight Controls - Uncommanded and Unarrested Flap Movement                                                                                                                             |
| BR-2025-09-02 | 2025-10-09 | EMBRAER S.A.                          | EMB-135                                    | [Correction] Airworthiness Limitations (Certification Maintenance Requirements, Airworthiness Limitation Inspections, Fuel System Limitation Items, and Life Limited Items) - Revision |
| US-2025-20-03 | 2025-10-09 | BOEING                                | 787                                        | Equipment / Furnishings - Lower Fitting Assemblies and Centerline Partition Threshold of Lavatories - Inspection / Revision of Maintenance Program                                     |
| US-2025-20-04 | 2025-10-09 | BOEING                                | 757                                        | Flight Controls - Aileron Trim Actuator - Repetitive Inspections / Modification                                                                                                        |
| US-2025-20-11 | 2025-10-09 | TEXTRON AVIATION INC.                 | 200 (Super King Air), 300 (Super King Air) | Flight Controls - Attaching Rivets of the Pilot and Copilot Rudder Control Pushrods - Inspection                                                                                       |
| BR-2025-10-01 | 2025-10-09 | EMBRAER S.A.                          | ERJ 190                                    | Engine Feed Check Valve - Inspections / Functional Test                                                                                                                                |
| 2025-0219     | 2025-10-06 | AIRBUS S.A.S.                         | A330                                       | Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 1 - Safe Life Airworthiness Limitation Items - Amendment                                                     |
| 2025-0218     | 2025-10-06 | AIRBUS HELICOPTERS                    | H160                                       | Equipment / Furnishings - Emergency Location Transmitter Mounting Tray - Replacement                                                                                                   |
| 2025-0216     | 2025-10-01 | AIRBUS S.A.S.                         | A330, A340                                 | Equipment / Furnishings - Doghouse Placard - Replacement                                                                                                                               |
| 2025-0217     | 2025-10-01 | AIRBUS HELICOPTERS DEUTSCHLAND        | BO 105, EASA STC 10039633, MBB-BK 117      | Rotors Flight Control - Fork Lever - Inspection                                                                                                                                        |



| Publ. number | Issue Date | TC Holder         | Type                                                     | Subject                                                                                                                                    |
|--------------|------------|-------------------|----------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|
| 2025-0215    | 2025-10-01 | ATR               | ATR42, ATR72                                             | Stabilizers - Vertical Stabilizer to Rudder Junction Ribs and Lugs -Inspection / Replacement (Wrong Material)                              |
| 2025-0214    | 2025-09-30 | AIRBUS S.A.S.     | A300-600                                                 | Time Limits / Maintenance Checks - Airworthiness Limitations Section - Part 2 / Damage Tolerant Airworthiness Limitation Items - Amendment |
| 2025-0200    | 2025-09-30 | DASSAULT AVIATION | Falcon 2000, Falcon 7X, Falcon 900EX, Mystère-Falcon 900 | [Correction] Equipment / Furnishings - Passenger Seats - Modification                                                                      |