



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2026-08	2026-02-12	AIRBUS CANADA LP	BD-500 (A220 Series)	Equipment/Furnishings - Overhead Stowage Compartment - Handle Rod Disconnected
CF-2026-09	2026-02-12	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Ice and Rain Protection - Engine Cowl Anti-Ice - Ejector Pipe Chafing
2026-0029	2026-02-12	AIRBUS HELICOPTERS	SA/AS 365 / EC 155	Tail Rotor Drive - Tail Gear Box Input Flange - Functional Checks
2026-0028	2026-02-11	AIRBUS S.A.S.	A318, A319, A320, A321	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment
2026-0027	2026-02-11	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2024-0215R1	2026-02-11	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Main Rotor - Hub Sleeves - Inspection
2025-0297R1	2026-02-10	APPLIANCES	ATA 35 OXYGEN	AEROSPACE & DEFENSE OXYGEN SYSTEMS SaS (Part of SAFRAN AEROSYSTEMS): Portable Breathing Equipment - Removal From Service
2026-0026	2026-02-10	AIRBUS S.A.S.	A340	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment
2026-0025	2026-02-10	AIRBUS S.A.S.	A330	Time Limits / Maintenance Checks - Airworthiness Limitations Section Part 2 - Damage Tolerant Airworthiness Limitation Items - Amendment
2025-0294R1	2026-02-09	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	B/E AEROSPACE FISCHER GmbH: Medical Seats - Modification
2025-0228R1	2026-02-06	DASSAULT AVIATION	Falcon 2000, Falcon 7X, Falcon 900EX	Standard Practices and Structures - DECOMATIC Titanium Bolts - Replacement
US-2026-02-10	2026-02-06	BOEING	787	Water / Waste - Faucet Control Module - Inspections / Replacement
CF-2026-07	2026-02-05	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Ice and Rain Protection - Engine Cowl Anti-Ice - Ejector Pipe Chafing
CF-2026-06	2026-02-05	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Landing Gear - Main Landing Gear Aft Door Mechanism - Lock Link Apex Pin/Bolt Fracture
2026-0024	2026-02-05	AIRBUS HELICOPTERS DEUTSCHLAND	EC135/635	Rotors Flight Control - Ball Bearing Control System - Inspections
CF-2025-60R1	2026-02-04	BELL TEXTRON CANADA LTD (BTCL)	429	Fuselage - Tail Rotor Gearbox Support Assembly to Tailboom Attachment Discrepant Rivets
2025-0283	2026-02-04	AIRBUS S.A.S.	A350	[Correction] Nacelles / Pylons - Air Intake Cowl - Inspection



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2026-05	2026-02-03	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	HONEYWELL ASCa Inc.: Emergency Locator Transmitter - Degraded Performance in High Temperature environment.
2026-0023	2026-02-02	TECNAM, Costruzioni Aeronautiche	P2010	Engine Exhaust - Noise Suppressor / Muffler - Inspections
CF-2026-04	2026-02-02	DE HAVILLAND AIRCRAFT OF CANADA LTD.	DHC-8	Landing Gear - Main Landing Gear Premature Tire Failure