



Publ. number	Issue Date	TC Holder	Type	Subject
2026-0076	2026-04-10	DAHER AEROSPACE	TBM 700	Landing Gear - Main Landing Gear Shock Strut Cylinder - Inspection / Replacement / Modification
2026-0075	2026-04-10	AIRBUS HELICOPTERS	EC175	Fuselage - Scuppers of the Engine Drain System - Modification
US-2026-06-71	2026-04-09	HONDA AIRCRAFT COMPANY LLC	HA-420	Flight Controls - Flap Control Pushrods - Replacement
BR-2026-04-01	2026-04-09	EMBRAER S.A.	ERJ 190	Time Limits / Maintenance Checks - Airworthiness Limitation Section / Maintenance Program - Revision
2026-0074	2026-04-08	AIRBUS S.A.S.	A350	Hydraulic Power - Engine-Driven Pump - Software Update / Modification Aircraft Flight Manual - Abnormal and Emergency Procedures - Amendment
2026-0072	2026-04-01	LEONARDO S.p.A. HELICOPTERS	AW189	Power Plant - Engine Mount Fitting - Inspections / Replacement
2026-0073	2026-04-01	AIRBUS S.A.S.	A330	[Correction] Fuel - Standby Fuel Pump - Operational Check
CF-2026-15	2026-03-31	BOMBARDIER	BD-700	Navigation - Head-Up Display Application Software Issue in Avionic Software Version 5.8 - Amendment
2026-0071	2026-03-31	TECNAM, Costruzioni Aeronautiche	P2006T	Powerplant - Engine Shock Mounts - Replacement
2026-0070-E	2026-03-30	PIPISTREL VERTICAL SOLUTIONS d.o.o.	Virus SW	Flight Controls - Airbrakes Bellcrank - Inspection