



Publ. number	Issue Date	TC Holder	Type	Subject
US-2026-13-51	2026-06-19	GULFSTREAM AEROSPACE CORPORATION	GVIII	Power Plant - Engine Mount System - Inspection
CF-2026-25	2026-06-19	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Indicating/Recording System - Misleading Caution Messages Posted on Engine Indicating and Crew Alerting System during Air Driven Generator Deployment
CF-2026-24	2026-06-19	AIRBUS CANADA LP	BD-500 (A220 Series)	Fire Protection - Main Wheel Well Bin Sensing Element - Incompatible Connector Nut - Replacement
2026-0117	2026-06-19	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT 1000	Engine - Low Pressure Turbine Discs - Inspection
US-2026-12-07	2026-06-18	BOEING	787	Auto Flight - Mode Control Panel - Replacement
2026-0095R1	2026-06-17	GUIMBAL, HELICOPTERES	CABRI	Main Rotor Drive - Main Rotor Mast - Inspection
US-2026-09-12	2026-06-16	BOEING	737	Fuselage - Aft Drain Mast Fuselage Skin - Inspections
2026-0112	2026-06-15	GROB AIRCRAFT SE	G 109	Fuel - Fuel Shut-off Valve - Inspection / Replacement
2026-0115	2026-06-15	LEONARDO S.p.A. HELICOPTERS	A109/A119	Stabilizers - Torque Tube Assembly - Inspection
2026-0116	2026-06-15	AIRBUS HELICOPTERS	H160	Doors - Emergency Exit Rope on the Jettisonable Window Systems - Cleaning
2023-0147R3	2026-06-15	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Time Limits / Maintenance Checks - Main Gearbox Suspension Bar Pins / Fittings - Re-calculation of Life Limits / Replacement / Modification Fuselage - Main Gearbox Suspension Bar Pins / Fittings - Replacement / Modification
2026-0114	2026-06-12	AIRBUS S.A.S.	A350	Landing Gear - Main Landing Gear Axles - Inspections
2026-0113	2026-06-11	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	TRENT XWB	Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Programme - Amendment
US-2026-10-02	2026-06-10	HONDA AIRCRAFT COMPANY LLC	HA-420	Fuselage - Airworthiness Limitations Section - Maintenance / Inspection
2026-0111	2026-06-10	AIRBUS HELICOPTERS	AS 350 / EC 130	Tail Rotor Drive - Shaft Sleeves - Inspection
2026-0110	2026-06-10	AIRBUS HELICOPTERS	EC175	[Correction] Fuselage - Screws and Nuts installed on Firewalls - Inspection
2026-0060R1	2026-06-09	AIRBUS S.A.S.	A330, A340	Fuel - Fuel Low Pressure Shut-Off Valve - Leak Check
US-2026-10-05	2026-06-08	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	Goodrich Cabin Attendant Seats - Replacement
US-2026-11-05	2026-06-08	SIKORSKY	S-61	Rotorcraft Flight Control - Auxiliary Servo Assembly - Inspections



Publ. number	Issue Date	TC Holder	Type	Subject
2026-0109	2026-06-08	AIRBUS HELICOPTERS DEUTSCHLAND, MECAER AVIATION GROUP SpA	MBB-BK 117, EASA STC 10051018	Oxygen - Low Pressure Oxygen Hoses - Replacement
2026-0104	2026-06-08	AIRBUS HELICOPTERS	H160	Rotorcraft Flight Manual - Limitations Section - Amendment
2026-0107	2026-06-08	AIRBUS DEFENCE & SPACE S.A.	C-295	Navigation - Radio Altimeter and Ground Proximity System Antennas - Modification