



Publ. number	Issue Date	TC Holder	Type	Subject
CF-2026-43	2026-09-11	MHI RJ Aviation ULC	CL-600 (Regional Jet)	Ice and Rain Protection - Wing Anti-Ice - Aircraft Flight Manual Procedure Anomaly - Amendment
CF-2026-45	2026-09-11	AIRBUS CANADA LP	BD-500 (A220 Series)	Wings - Discrepant Fasteners at Wing to Fuselage Joint - Amendment
2026-0176	2026-09-11	AIRBUS S.A.S.	A318, A319, A320, A321	Electrical Systems Installation - Battery Retaining Rods - Identification / Replacement
2026-0144R1	2026-09-11	AIRBUS S.A.S.	A320, A321	Stabilizers - Rudder Outer Skin - Inspection
2026-0175	2026-09-10	LEONARDO S.p.A. HELICOPTERS	AB212/AB412	Rotor(s) - Main Rotor Yoke - Inspection
G-2026-0004	2026-09-09	APPLIANCES	ATA 25 EQUIPMENT / FURNISHINGS	TECHTEST - HR SMITH GROUP - Equipment / Furnishings - Personal Locator Beacon / Emergency Location Transmitter - Inspection
2026-0174	2026-09-08	CFM INTERNATIONAL	CFM56-7B	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2026-17-08	2026-09-08	PRATT & WHITNEY	PW4070, PW4080, PW4090	Turbine - High-Pressure Compressor Drum Rotor Disk - Inspection / Replacement
BR-2026-08-01	2026-09-07	EMBRAER S.A.	ERJ 170	Time Limits / Maintenance Checks - Airworthiness Limitation Section / Maintenance Program - Revision
G-2026-0005	2026-09-07	BAE SYSTEMS (OPERATIONS) LTD	AVRO146RJ, BAE146	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
US-2026-17-02	2026-09-07	BOEING	787	Wings - Lower Outboard Wing Skin - Inspections
US-2026-16-06	2026-09-07	AVIATION PARTNERS BOEING, BOEING	EASA STC 10016394, STC ST01920SE, 767	Wings - Lower Outboard Wing Skin - Inspection
2026-0173-E	2026-09-04	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 800	Engine Oil - Oil Pump - De-Pairing
2026-0171	2026-09-04	DASSAULT AVIATION	Falcon 7X	Time Limits / Maintenance Checks - Airworthiness Limitations Section - Amendment
2026-0172-E	2026-09-04	ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG	RB211 TRENT 700	Engine Oil - Oil Pump - De-Pairing
CF-2026-42	2026-09-03	DE HAVILLAND AIRCRAFT OF CANADA LTD.	CL-215	Flight Controls - Elevator Trim-Feel Assembly - Bonding Jumper Interference with Elevator Controls - Replacement
CF-2026-40	2026-09-02	AIRBUS CANADA LP	BD-500 (A220 Series)	Time Limits/Maintenance Checks - New and Revised Airworthiness Limitations Tasks



Publ. number	Issue Date	TC Holder	Type	Subject
2026-0170	2026-09-01	BREEZER AIRCRAFT GmbH & Co. KG., CZECH SPORT AIRCRAFT , EVEKTOR, SPOL. S R.O., TOMARK, s.r.o.	B600, PS-28 Cruiser, SportStar RTC, Viper SD-4	Engine - Propeller Gearbox - Inspection
CF-2026-44	2026-09-01	PRATT & WHITNEY CANADA	PW307	Engine - High Pressure Turbine - 1st and 2nd- Stage Disks Suspected Material Defect - Replacement
US-2026-17-10	2026-08-31	LYCOMING ENGINES	IO-540, O-235, O-540	Reciprocating Engine - Piston Pin - Replacement
US-2026-15-02	2026-08-31	BOEING	777	Fuel - Lightning Protection for Engine Fuel Feed System - Inspections