


EASA	PROPOSED AIRWORTHINESS DIRECTIVE	
	<p>PAD No.: 06 - 232</p> <p>Date: 05 October 2006</p>	
No person may operate an aircraft to which an Airworthiness Directive applies, except in accordance with the requirements of that Airworthiness Directive unless otherwise agreed with the Authority of the State of Registry.		
Type Approval Holder's Name:		Type/Model designation(s):
BAE SYSTEMS (OPERATIONS) LTD		BAe 146 and Avro 146-RJ
TCDS Number: UK BA16		
Foreign AD: None		
Supersedure: None		
ATA 25	Equipment & Furnishings - Flight Deck ECS Grilles – Introduction of Bolt Attachment	
Manufacturer(s):	BAE Systems (Operations) Ltd, British Aerospace plc, British Aerospace (Commercial Aircraft) Ltd, British Aerospace (Operations) Ltd, British Aerospace Regional Aircraft Ltd, British Aerospace Regional Aircraft trading as Avro International Aerospace.	
Applicability:	All models BAe 146 and AVRO 146-RJ Series aeroplanes which have modification HCM00674A embodied.	
Reason:	There are four ECS grilles located in the flight deck side consoles. There have been occurrences where a grille has become detached during flight. There is a risk that a loose grille could foul the rudder pedals and interfere with rudder/ brake control resulting in an unsafe condition.	
Effective Date:	[TBD 14 days after final AD issue date]	
Compliance:	Within six months of the effective date of this AD carry out the modification described in BAe Systems (Operations) Service Bulletin 25-495-60730A or later approved revision.	
Ref. Publications:	BAe Systems (Operations) Limited Inspection Service Bulletin 25-495-60730A or later approved revision.	

Remarks :	<ol style="list-style-type: none"> 1. If requested and appropriately substantiated the responsible EASA manager for the related product has the authority to accept Alternative Methods of Compliance (AMOC) for this AD. 2. Closing date for comment is 03 November 2006. 3. Enquiries regarding this Airworthiness Directive should be referred to Mr M. Capaccio, Airworthiness Directive Focal Point – Certification Directorate, EASA, E-mail: ADs@easa.europa.eu 4. For any questions concerning the technical content of the requirements in this AD, please contact Project Management Group, Customer Information Department, BAE SYSTEMS (OPERATIONS), Prestwick International Airport, Ayrshire, KA9 2RW, Scotland. Ph: +44 1292 675207, Fax: +44 1292 675704, E-mail: RApublications@baesystems.com
-----------	--