

EASA	NOTIFICATION OF A PROPOSAL TO ISSUE AN AIRWORTHINESS DIRECTIVE
	PAD No.: 11-124 Date: 23 November 2011 Note: This Proposed Airworthiness Directive (PAD) is issued by EASA, acting in accordance with Regulation (EC) No 216/2008 on behalf of the European Community, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.
In accordance with the EASA Continuing Airworthiness Procedures, the Executive Director is proposing the issuance of an EASA Airworthiness Directive (AD), applicable to the aeronautical product(s) identified below. All interested persons may send their comments, referencing the PAD Number above, to the e-mail address specified in the 'Remarks' section, prior to the consultation closing date indicated.	
Type Approval Holder's Name : AIRBUS	Type/Model designation(s) : A318, A319, A320 and A321 aeroplanes
TCDS Number: EASA.A.064	
Foreign AD: Not applicable	
Supersedure: This AD supersedes EASA AD 2006-0162 dated 08 June 2006.	
ATA 05	Time Limits and Maintenance Checks – Safe Life Airworthiness Limitation Items – ALS Part 1 – Amendment
Manufacturer(s):	Airbus (formerly Airbus Industrie)
Applicability:	Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-111, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers.
Reason:	The airworthiness limitations for Airbus aeroplanes are currently published in Airworthiness Limitations Section (ALS) documents. The airworthiness limitations applicable to the Safe Life Airworthiness Limitation Items (SL ALI) are specified in Airbus A318/A319/A320/A321 ALS Part 1, which is approved by the European Aviation Safety Agency (EASA). EASA AD 2006-0162 was issued to require the implementation of the instructions and airworthiness limitations as specified in Airbus A318/A319/A320/A321 ALS Part 1 original issue. Failure to comply with the instructions of ALS Part 1 could result in an unsafe condition. This AD retains the requirements of EASA AD 2006-0162, which is superseded, extends the applicability by adding the Models A318-121, A318-122, A320-215 and A320-216, and requires the implementation of the instructions and airworthiness limitations as specified in Airbus A318/A319/A320/A321 ALS part 1 revision 02, approved on 13 May 2011.
Effective Date:	[TBD: 14 days after Final AD issue date]

Required Action(s) and Compliance Time(s):	Required as indicated, unless accomplished previously: (1) Within the compliance times defined in the Record of Revisions (ROR) pages of the Airbus A318/A319/A320/A321 ALS Part 1 revision 02, comply with all applicable instructions included by reference in the ROR of the Airbus A318/A319/A320/A321 ALS Part 1 revision 02. (2) Compliance with the requirements of paragraph (1) of this AD can be demonstrated by: (2.1) Revising as follows the approved Aircraft Maintenance Programme, on the basis of which the operator or the owner ensures the continuing airworthiness of each operated aeroplane: Incorporate all instructions and associated airworthiness limitations specified in Airbus A318/A319/A320/A321 ALS Part 1 revision 02, and that are relevant to the respective combination of aeroplane model and weight variant, and (2.2) Complying with the approved Aircraft Maintenance Programme described in paragraph (2.1) of this AD.
Ref. Publications:	A318/A319/A320/A321 ALS Part 1 Revision 02 approved on 13 May 2011. The use of later approved variations or revisions of this document is acceptable for compliance with the requirements of this AD.
Remarks :	1. This Proposed AD will be closed for consultation on 21 December 2011. 2. Enquiries regarding this PAD should be referred to the Safety Information Section, Executive Directorate, EASA; E-mail ADs@easa.europa.eu. 3. For any question concerning the technical content of the requirements in this PAD, please contact: AIRBUS – Airworthiness Office – EIAS; Fax +33 5 61 93 44 51; E-mail: account.airworth-eas@airbus.com.