



Publ. number	Issue Date	TC Holder	Type	Subject
DCA-750XL-26	2018-02-23	PACIFIC AEROSPACE LTD	750XL	Rudder and Elevator Trim Drive Coupling - Modification
DCA-750XL-25	2018-02-23	PACIFIC AEROSPACE LTD	750XL	Wing Leading Edge Tank Abrasion - Inspection
DCA-750XL-22A	2018-02-23	PACIFIC AEROSPACE LTD	750XL	Ventilation Hose behind Instrument Panel - Inspection
DCA-750XL-18B	2018-02-23	PACIFIC AEROSPACE LTD	750XL	Fin Forward Pickup - Inspection
2015-0135R2	2018-02-23	AIRBUS	A318, A319, A320, A321	Navigation - Angle of Attack Sensors - Replacement
DCA-750XL-27	2018-02-23	PACIFIC AEROSPACE LTD	750XL	Firewall Sound Insulation - Inspection
2018-0045	2018-02-22	AIRBUS	A350	[Correction] Fuselage / Stabilizer - Vertical Stabilizer Tension Bolts - Modification
CF-2018-06	2018-02-21	BOMBARDIER	CL-600 (Challenger)	Floodlight Panel - Cockpit Floodlight Water Penetration
US-2018-03-10	2018-02-20	BOEING	757	Fuselage - Skin Scribe Line Damage - Inspection
2018-0046	2018-02-19	AIRBUS HELICOPTERS DEUTSCHLAND	MBB-BK 117	Tail Rotor Drive - Tail Gear Box - Inspection / Replacement
2018-0044	2018-02-14	SAFRAN HELICOPTER ENGINES	ARRIUS 2	Engine - Gas Generator (Module 02) / Power Turbine Wheel - Replacement
2018-0042	2018-02-14	AIRBUS HELICOPTERS	SA 330 / AS 332 / EC 225	Tail Rotor Hub Assembly - Inspection
US-2018-01-01	2018-02-14	BOEING	MD-11	Fuel - Tail Fuel Tank Transfer Pump Wire Assemblies - Inspection
US-2018-03-03	2018-02-14	TEXTRON AVIATION INC.	401, 402, 411, 414, 421, 425 (Conquest)	Wings - Lower Forward Carry Through Spar Cap - Inspection / Replacement
2018-0043	2018-02-14	AIRBUS	A380	Power Plant - Rear Engine Mount Assembly - Inspection
2018-0040	2018-02-13	EVEKTOR, SPOL. S R.O.	SportStar RTC	Reciprocating Engine - Valve Push Rod Assembly - Inspection / Replacement